

# Epodur<sup>®</sup> 1870 Zinc-Rich Coating

# Description

Epodur 1870 protects metal surfaces with a film of sacrificial zinc in a manner similar to hot dip galvanizing. It is a zinc-rich coating based on an epoxy-ester resin. The dried film contains 93% zinc by weight. Epodur 1870 protects steel surfaces subjected to a wide variety of corrosive influences, and is particularly useful for recoating or spot-priming weathered or damaged galvanized surfaces. It has excellent recoating properties.

## Uses

- Electrical transmission towers and related structures
- Structural steel: bridges, buildings, offshore rigs
- Chemical process piping and equipment
- Pulp and paper equipment
- Oil and gas production, processing, and distribution equipment

#### Features

- Maximum content in dry film
- Easy brush or spray application
- Simple handling-single package epoxy system
- No pot life limitation
- Easy mixing-no hard settling of pigment
- Excellent wetting and penetration properties
- Flexible films with excellent adhesion
- Air dries quickly-set to touch in one hour
- Up to 5 mils dry film thickness per coat
- Can be applied over a wider range of temperatures and relative humidities than two-component epoxies

# **Surface Preparation**

*Steel:* For best results, surfaces should be free from oil, grease, dirt, mill scale, rust, corrosion products, oxides, paint and foreign matter. Abrasive blast surface to commercial grade per Steel Structures Painting Council Specification SSPC-SP6, "Commercial Blast Cleaning," or per NACE specification No. 3. If abrasive blasting can not be permitted, remove loose mill scale, loose rust, and loose paint per Specification SSPC-SP3, "Power Tool Cleaning."

*New Galvanized Surfaces:* remove all oil, grease and flux by solvent cleaning per Specification SSPC-SP1, "Solvent Cleaning."

Weathered Galvanized Surfaces: Remove all dirt, oil and grease by solvent cleaning. Remove rust or foreign deposits by wire brushing per Specification SSPC-SP2, "Hand Tool Cleaning", or power tool cleaning per Specification SSPC-SP3, "Power Tool Cleaning."

#### Mixing

Stir thoroughly until the zinc dust content is completely dispersed.

# **Application Guidelines**

Epodur 1870 may be applied by brush, spray, or roller. Airless spray is not recommended because of possible tip clogging. Thinning is not normally required.

Steel: Apply one coat to 2.5-3 mils dry film thickness.

*New Galvanized Surfaces:* Apply one coat to 2.5-3 mils dry film thickness

*Rusted Galvanized Surfaces:* Apply a second coat to 2.5-3 mils dry film thickness, total system dry film thickness of 5-6 mils. Allow 12 hours dry time between coats.

# **Drying Time**

At room temperature, Epodur 1870 sets to touch in one hour and may be recoated after 12 hours.

# **Application Equipment**

*Brush:* Apply after thorough mixing. If thinning is required, use up to one pint, maximum of Dampney 105 Thinner per gallon. Mix thoroughly after thinner addition.

*Roller:* Apply after thorough mixing. Use rollers with short nap. Cross roll for uniform coverage. If thinning is required use up to one pint, maximum of Dampney 105 Thinner per gallon.

*Conventional Spray Equipment:* Apply after thorough mixing. If thinning is required use up to one pint maximum per gallon of Dampney 105 Thinner.

| As a guide only    |                        |
|--------------------|------------------------|
| Spray Gun          | DeVilbiss P-MBC or JGA |
| Fluid hose*        | 3/8" I.D.              |
| Air hose           | 5/16" I.D.             |
| Air cap            | 704                    |
| Fluid nozzle       | FF(.055")              |
| Pot pressure       | 10-15 lbs.             |
| Atomizing pressure | 45-50 lbs.             |
| Needle adjustment  | Full open              |
| Work distance      | 8-10"                  |
|                    |                        |

\*Smaller diameter hoses, or hose lengths greater than 25 feet, may require increased pressure.

# Storage

Store in a cool, dry place, preferably below 80°F

## Clean up

Clean equipment with Dampney 100 Thinner.

## **Precautionary Information**

Keep away from heat, sparks, and open flame. Use only with adequate ventilation. Avoid contact with eyes and skin. Avoid prolonged breathing of vapor or spray mist.

FIRST AID: In case of contact with skin, flush with plenty of water. For eyes, immediately flush with plenty

#### Bulletin 1870

of water for 15 minutes and get medical attention. If exposed to high concentration of vapor, remove to fresh air. If swallowed, CALL A PHYSICIAN IMMEDIATELY. DO NOT induce vomiting. In confined spaces, observe safety precautions and follow procedures described in OSHA regulations.

Provide adequate forced air ventilation. Require workmen to wear NIOSH-approved air line respirator, and non-sparking footwear. Use only non-sparking tools and equipment. Use only explosion-proof lights and electrical equipment. Make certain all equipment is grounded. Use protective clothing and skin cream. For further information on safety precautions, see appropriate Material Safety Data Sheet (MSDS).

## Not Recommended For

- Do not use in severe service without topcoating. Consult your Dampney representative for recommendations.
- Immersion Service

#### FOR INDUSTRIAL USE ONLY

| Shipping Weights    | 1's     | 2's     | 5's     |
|---------------------|---------|---------|---------|
| Epodur 1870         | 25 lbs. | 50 lbs. |         |
| Dampney 105 Thinner | 8 lbs.  |         | 40 lbs. |

| Technical Data                             |                       |  |  |
|--|-----------------------|--|--|
| Characteristics                            | Endcor 1870           |  |  |
| Color                                      | Metallic Gray         |  |  |
| Finish                                     | Flat                  |  |  |
| Weight per gallon                          | 24 lbs.               |  |  |
| % Solids by volume                         | 50                    |  |  |
| Theoretical coverage per gallon*           | 800 mil sq ft         |  |  |
| Operating temperature range                | -40°F to +180°F (dry) |  |  |
| Surface temperature at time of application | 50°F minimum          |  |  |
| Dry film thickness per coat                | 2.5-3 mils            |  |  |
| Wet film thickness per coat                | 5-6 mils              |  |  |
| Surface temperature at time of application | 50°F minimum          |  |  |
| Dry film thickness per coat                | 2.5-3 mils            |  |  |
| Wet film thickness per coat                | 5-6 mils              |  |  |
| Flash Point (Pensky-Martens)               | 101°F minimum         |  |  |
| Drying time at 70°F                        |                       |  |  |
| Set to touch                               | 1 hour                |  |  |
| Recoat time                                | 12 hours              |  |  |
| Shelf Life                                 | 1 year                |  |  |

\*Note: actual coverage rate will vary depending upon material losses during mixing and application, and upon type and condition of surface to be coated. See Bulletin 3110 "Calculating Coating Requirement" for additional information.

**Warranty** Dampney protective coating products are expressly warranted to meet applicable technical and quality specifications. The Technical data contained herein are accurate at the date of issuance but are subjected to change without prior notification. No warranty of current accuracy is hereby given or implied. User must contact Dampney to verify correctness before ordering. Dampney assumes no responsibility for coverage, performance or injuries resulting from handling or use and LIABILITY, IF ANY, SHALL BE LIMITED TO PRODUCT REPLACEMENT. In no event will Dampney be responsible for consequential damages, except insofar as mandated by law. Dampney DISCLAIMS ALL OTHER WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.